TSHART-1620m

Safe 0-20 mA and 4-20 mA analog input FTA with HART interface (16 channels)

Description

Field termination assembly module TSHART-1620m is the interface between field components (sensors, etc.) and the safe high-density analog input module SAI-1620m in Safety Manager. The FTA provides HART interface. It can be used for interfacing signals from Class I, division 2 Hazardous Locations.

The TSHART-1620m module has sixteen analog input channels, which may be used for both safety-related and non-safety-related applications. These sixteen channels (separated into two groups of eight channels with common 0 V) are connected via a system interconnection cable (SICC-0001/Lx), which is plugged into the SIC connector on the FTA module, and connects to a (redundant pair of) SAI-1620m module(s).

The FTA module has a universal snap-in provision for standard DIN EN rails, and screw terminals for connection of power supply, ground and field wiring.




Figure 326 Mechanical layout

Main functions

The TSHART-1620m module has four main functions:

- Linear direct conversion of 0(4)—20 mA DC field signals to the signal levels of the safe high-density analog input module SAI-1620m
- Enable connection to HART multiplex units of MTL or Pepperl+Fuchs (P+F)
- Power supply distribution to each transmitter with voltage-current limitation in compliance with Hazardous Area Class I Division 2
- Enable monitoring of the external power connected to the FTA module

Linear direct conversion

The input circuit of each channel consists of a high-precision resistor, which converts the input current (0-20 mA) to the input voltage for the high-density analog input module SAI-1620m. The power to the analog transmitter is supplied via a series resistor. Each analog signal has its own terminal for the field cable shield. Figure 327 on page 545 shows the schematic diagram for connecting a transmitter (active and passive).




Figure 327 Schematic diagram for connecting a transmitter

HART interface

 Warning:

 Suggested HART multiplexers have no galvanic isolation between (24 Vdc) supply and the HART signals (common 0 Vdc).

The TSHART-1620m module provides an interface to HART multiplex units from MTL and P+F. Special connectors are installed on the FTA for connection of the standard cables from these suppliers.

The following connections and equipment can be used:

MTL solution:

- Multiplex unit MTL4842
- Cable: MTL FLAT20-2.2
- Connector on FTA: CN2 (see Figure 326 on page 543)

P+*F* solution:

- Multiplex unit KFD0-HMS-16 or KFD2-HMM-16
- Cable: K-HM26
- Connector on FTA: CN3 (see Figure 326 on page 543)

Class I division 2

The TSHART-1620m module may be used for non-incendiary field circuits to Class I, division 2 applications. The external output voltage (V+) is current-limited by means of a series resistor.

Transmitter voltage

Figure 328 on page 546 shows the available transmitter voltage for passive transmitters.




Figure 328 Transmitter voltage for passive transmitters

External power

If all inputs are active, no external power is required.

For loops, which contain passive transmitters, analog process data is only available if the supply voltage to the electronics is guaranteed. The high-density analog input concept (using TSHART-1620m / TPSU-2430 modules) offers full monitoring of power that is provided externally. If DC/DC converter modules TPSU-2430 are used, even redundant power supplies are covered.

Redundant external power can be connected to the TSHART-1620m module via two screw terminal pairs marked '1A', '1B', '2A' and '2B'. The screw terminal pairs are interconnected on the FTA module but de-coupled via diodes. The sixteen channels on the FTA module are divided into two groups of eight channels, with each group being protected by a 315 mA fuse. Single-channel errors (shorts from V+ to 0 V) cannot blow the group fuse.

X

Note

The 0 V connection of the external power is directly connected to the common 0 V of all sixteen analog inputs.

The Safety Manager application software must monitor the external power voltage via the safe high-density analog input module SAI-1620m when safety-related analog input signals are connected to the TSHART-1620m.

Figure 329 on page 547 shows the schematic diagram for power distribution with monitoring.




Figure 329 Schematic diagram for power distribution with monitoring

Applications

For details on applications and connection options for the TSHART-1620m module see "SICC-0001/Lx" on page 715.

Connections

External power and ground

The redundant external supply voltage (Vext) and ground are connected to the following screw terminals (marked '1A', '1B', '2A', '2B' and ' \downarrow ' on the FTA):

Screw terminal	Function	
1A	30 Vdc Vext feeder 1	
1B	0 Vdc Vext feeder 1	
2A	30 Vdc Vext feeder 2	
2B	0 Vdc Vext feeder 2	
Ŧ	Ground connection	
Ŧ	Ground connection	
	(1 ground wire is enough)	

Connections diagram

Figure 330 on page 549 shows the connections diagram of the TSHART-1620m module.

The TSHART-1620m module has sixteen groups (= sixteen channels) of four screw terminals to provide optimum connection of field wiring, with a ground terminal per channel for screening of analog input cables. The screw terminals are numbered 1 to 64.

SIC connector				Field termina	
Signal				Signal	Terminal
	315mAT			Ground	
1A 30Vdc 1 -			Į	Ground Ground	+ +
1B 0 Vdc					<u> </u>
2B 0 Vdc -	315mAT	R	-	- IN1 (v+)	1
30 Vdc ext.	þ. þ.	Hart1 ←		- IN1 (ground)	+ 3
				IN1 (mA input) IN1 (0 Volt)	4
		R		- IN2 (v+)	5
		Hort2 ←		IN2 (ground) IN2 (mA input)	+
MTL Hart-				IN2 (mA input) IN2 (0 Volt)	8
interface Hort1 Hort2				- IN3 (v+)	9
Hart3 Hart4		Hart3 ←		IN3 (ground) IN3 (mA input)	+ 1
Hart5 Hart6				- IN3 (0 volt)	12
Hart7 Hart8 Hart9 Hart10		R		- IN4 (v+)	13
Hart11 Hart12		Hart4 🔶		IN4 (ground) IN4 (mA input)	+ 15
Hart13 Hart14				- IN4 (0 volt)	16
Hart15 Hart16 O Volt O Volt		Hart5 ←		- IN5 (v+)	1
0 Volt 0 Volt		Harts -	→□□→	IN5 (ground) IN5 (mA input)	19
20-pole conn.				IN5 (0 volt)	20
		Hart6 ←		IN6 (v+) IN6 (ground)	2
		Hurto		IN6 (ground) IN6 (mA input)	2
A10 0 Vdc				IN6 (0 volt)	24
A9 IN1 -	$\vdash \downarrow \downarrow $	Hart7 ←	╶╴╢╢╴╴╴╸	IN7 (V+) IN7 (ground)	2!
B9 IN2 -				- IN7 (mA input)	2
B8 IN4		_		- IN7 (0 volt)	28
A7 IN5 -		Hart8 ←		IN8 (V+) IN8 (ground)	29
B7 IN6			→□□→	IN8 (mA input)	3
B6 IN8			R	IN8 (0 volt)	3:
A5 IN9 -		R		IN9 (v+)	3
B5 IN10		Hart9 ←		IN9 (ground)	÷
B4 IN12 -				IN9 (mA input) IN9 (0 Volt)	3
A3 IN13		R	⊐ □	- IN10 (v+)	3
A2 IN15		Hart10 ←		- IN10 (ground)	-+
B2 IN16 -				IN10 (mA input) IN10 (0 Volt)	4
A1 0 Vdc		R		– IN11 (v+)	4
0.		Hart11 ←		IN11 (ground) IN11 (mA input)	
				IN11 (mA input) IN11 (0 Volt)	4.
		R		- IN12 (v+)	4
		Hort12 ←		IN12 (ground) IN12 (mA input)	4
P&F Hart-				IN12 (0 Volt)	48
interface		Hart13 ←		- IN13 (v+)	49
0 Volt 0 Volt		nurtið 🛀	→□□→	IN13 (ground) IN13 (mA input)	5
0 Volt 0 Volt 0 Volt Hart1		_		- IN13 (0 Volt)	52
Hart2 Hart3		Hart14 ←	⊒	IN14 (V+) IN14 (ground)	5.
Hart4 Hart5 Hart6 Hart7		10111	→□□→│┤	IN14 (mA input)	5
Harte Hart/ Harte 0 Volt		_	_└⊡ ┼┤	- IN14 (0 volt)	56
0 Volt Hart9		Hart15 ←		IN15 (V+) IN15 (ground)	5
Hart10 Hart11 Hart12 Hart13			→ਛੈੈੈ	- IN15 (mA input)	59
Hart12 Hart13 Hart14 Hart15		_	┓┶═╍╸┽┤	- IN15 (0 volt)	60
Hart16 0 Volt	'	Hart16 ←	┛╺╺┍	IN16 (V+) IN16 (ground)	6 +
0 Volt 0 Volt 26-pole conn.			⊣⊡_∔	IN16 (mA input)	6.
zo pole contr.	1			IN16 (0 Volt)	64

Figure 330 Connections diagram

Technical data

General	Type numbers ¹ :	FS-TSHART-1620m			
		FC-TSHART-1620m			
	Approvals:	CE, TUV, UL, CSA, FM			
Input	Number of input channels:	16 (2 groups of 8 with common 0 V			
	Power requirements:	30 Vdc external, 3 mA (without input loop loads)			
	Input current:	0—25 mA			
	Input resistance:	250 Ω (± 1%)			
Output	To passive transmitters (Vext):				
	Output resistance:	270 Ω (± 5%)			
	• Igniting current per channel:	< 120 mA at 30 Vdc			
	To SAI-1620m module:				
	Output voltage	0-4 Vdc			
	Accuracy	0.1%			
	To HART multiplex unit:				
	Output voltage	Max. 5 V peak-peak			
	Series impedance	> 100 nF			
Fuses	Rating:	315 mAT (slow-acting)			
	Dimensions:	5 × 20 mm (0.20 × 0.79 in)			
Physical	Module dimensions:	$250 \times 70 \times 60 \text{ mm} (L \times W \times H)$			
		$9.84 \times 2.76 \times 2.36$ in (L × W × H)			
	DIN EN rails:	TS32 / TS35 × 7.5			
	Used rail length:	251 mm (9.87 in)			
Termination	Screw terminals:				
	• Max. wire diameter	2.5 mm ² (AWG 14)			
	Strip length	7 mm (0.28 in)			
	Tightening torque	0.5 Nm (0.37 ft-lb)			

The TSHART-1620m module has the following general specifications:

1 FS-type modules are non conformal coated modules.

FC-type modules are conformal coated modules. Conformal coated modules have the letters "CC" preceding the version number.